



UNITED STATES ENVIRONMENTAL PROTECTION AGENCY

REGION 4  
ATLANTA FEDERAL CENTER  
61 FORSYTH STREET  
ATLANTA, GEORGIA 30303-8960

JAN 28

UNITED PARCEL SERVICE

Mr. Bob McCaughtry  
A&M Contracting, LLC  
1458 Grist Mill Drive  
Acworth, Georgia 30101

Dear Mr. McCaughtry:

Enclosed is a copy of the final inspection report generated by the U.S. Environmental Protection Agency's Region 4 for the inspection conducted on December 18, 2019, for a demolition site located at 720 Neese Road in Woodstock, Georgia. The inspection was conducted in accordance with Section 114 of the Clean Air Act to determine compliance with the Asbestos National Emission Standard regulations at 40 C.F.R. Part 61, Subpart M. During the inspection, no claims of Confidential Business Information were asserted that impact the information contained in this report.

Please contact Pamela Storm at 404-562-9197 or by email at [storm.pamela@epa.gov](mailto:storm.pamela@epa.gov) if you have any questions.

Sincerely,

A handwritten signature in black ink, appearing to read "Todd Russo", with a long horizontal flourish extending to the left.

Todd Russo  
Chief  
Air Enforcement Branch

Enclosure

cc: Jennifer Vogel, Program Manager  
Lead-Based Paint and Asbestos Program



## INSPECTION REPORT

**Facility Inspected** 720 Neese Road  
Woodstock, Georgia 30188

**Inspection Date:** December 18, 2019

**Facility Programmatic ID #** 04000EPAGAASB720;  
LAT: 34.0991 LON: -84.4914

**Inspection Type** Clean Air Act (CAA)  
National Emission Standards for Hazardous Air Pollutants (NESHAP) - Asbestos

**Inspector** Pamela Storm

### Introduction

An inspection pursuant to Section 114 of the CAA was conducted on December 18, 2019, at a demolition site located at 720 Neese Road in Woodstock, Georgia (the facility). The facility is owned by the City of Woodstock. The facility had been demolished at the time of this inspection. A&M Contracting, LLC obtained permit #PDEMO-000021-2019 for the demolition of the facility from the City of Woodstock. The inspector obtained a copy of this permit from the City of Woodstock on December 18, 2019, prior to this inspection. The inspection was conducted by Pamela Storm who possesses EPA inspector credentials to conduct CAA NESHAP asbestos inspections. The purpose of the inspection was to determine compliance with the CAA NESHAP asbestos standards and the regulations promulgated at 40 CFR Part 61, Subpart M, for the demolition activity conducted pursuant to this permit.

The EPA Region 4 CAA NESHAP asbestos program targets facilities for inspection located in the State of Georgia based on tips/complaints; permits issued on a local level; and demolition and/or renovation/abatement notices sent to the State. This inspection was conducted based on the aforementioned permit.

### Facility Information

The facility had been demolished at the time of inspection. It could not be determined what the facility had been previously used for at the time of this inspection.

### Inspection

#### Inspection


It appeared that the facility had been demolished at the time of this inspection. At the time of this inspection, an employee with Atlanta Gas and Light Company was at the site disconnecting the service to the property. He did not know for what purpose the facility had been previously used. He also did not know when the demolition of the facility occurred. Demolition equipment was at the site. No demolition debris was present at the time of this inspection. The aforementioned permit indicated that the permitted activity would occur from December 11, 2019, through December 10, 2020.

## Conclusion

The inspector will follow up with the owners/operators as deemed appropriate to obtain information and necessary paperwork related to this demolition activity.


## Report Approval

This inspection report was written by:

  
Pamela Storm, Lead Inspector

1/21/20  
Date

This inspection report was approved by:

  
Todd Russo, Chief  
Air Enforcement Branch

1/24/2020  
Date